

Neighborhood Cluster Planning Sector 6


Neighborhood/Commercial Building Conditions by Block Face

- Stable Conditions
- Beginning Signs of Decline
- Advanced Signs of Decline
- Major Signs of Deterioration

Figure #16 Neighborhood/Commercial Building 82







Michigan Metropolitan Information Center 1997